

Better chemistry. Better business.

Hubbard-Hall Inc. • 563 South Leonard Street, Waterbury, CT 07608 • HubbardHall.com • 800-648-3412

Product Bulletin

Product Name: Acid Brite 40 Product Code: 2541011 Revision Date: May 15, 2020

Acid Brite 40

Acid Brite 40 is an acid cleaner and deoxidizer for aluminum and stainless-steel surfaces. It contains a blend of inorganic acids, surfactants and solvents to remove heavy soils quickly and effectively. It may also be used to descale steel surfaces.

Acid Brite 40 is extremely free rinsing and may be used in soak or spray applications. It is safe when used as directed. All surfactants used in Acid Brite 40 are biodegradable.

Features & Benefits

Non-fuming	Safer to work with
	Longer equipment life
High strength	Carry less inventory
Clean and	Process versatility
deoxidize	
High quality	Consistent quality and
materials	performance

Typical Applications

- Job shops that have aluminum or stainless-steel parts
- On site truck washes for brightening aluminum
- On site truck washes for cleaning and brightening stainless-steel
- Difficult to treat parts with heavy scale or oxide.

Operating Conditions

Spray	2-15% volume
Soak	5% volume to full strength

Test Kit Method

- 1. Transfer 5 mL of the Acid Brite 40 solution to the test bottle with the syringe.
- 2. Add 10 mL of tap water to the beaker.
- 3. Add 5 to 8 drops of the Phenolphthalein Indicator to the test bottle.
- 4. While swirling the solution in the test bottle, add the 12N Sodium Hydroxide dropwise, counting the drops. Continue adding the Sodium Hydroxide until the solution turns pink.









Better chemistry. Better business.

Hubbard-Hall Inc. • 563 South Leonard Street, Waterbury, CT 07608 • HubbardHall.com • 800-648-3412

Product Bulletin

Product Name: Acid Brite 40 Product Code: 2541011 Revision Date: May 15, 2020

5. Record the number of drops. Calculation

Concentration = # Drops 12N NaOH x 0.86

Caution

Equipment: Plastic containers must be used. Tanks should be vented.

Do not allow product to dry on work surface. Acid Brite 40 will etch glass, especially if allowed to dry. Do not use this product on chrome, tin, zinc, galvanized or magnesium. If used to clean transportation equipment, always work from the bottom up to prevent staining.

Strong acid. Avoid contact with skin or eyes. Not to be taken internally. Contains fluorides.

Read and understand OSHA safety data sheet prior to using or working with this product. People handling and working with this product should be properly trained in safe handling of corrosive liquid acids. Eye wash and safety shower should be readily accessible in areas in which this product is used, handled and stored.

WARRANTY: THE QUALITY OF THIS PRODUCT IS GUARANTEED ON SHIPMENT FROM OUR PLANT. IF THE USE RECOMMENDATIONS ARE FOLLOWED, DESIRED RESULTS WILL BE OBTAINED. SINCE THE USE OF OUR PRODUCTS IS BEYOND OUR CONTROL, NO GUARANTEE EXPRESSED OR IMPLIED IS MADE AS TO THE EFFECTS OF SUCH USE, OR THE RESULTS TO BE OBTAINED.

Our people. Your problem solvers.

For more information on this process please call us at 1-800-648-3412

or techservice@hubbardhall.com











